## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner not set in original survey.

J-2
DIAGRAM
T2S R36E
W1/16
- <u>S 7</u> S 18

No record of subsequent monumentation found in County records. Description of corner evidence found:

NONE

See map of survey dated 5/19/80

Description of monument and accessories I established to perpetuate the original location of this corner:

At proportionate distance I set a  $2\frac{1}{2}$  inch x 30 inch iron pipe with brass cap marked as shown, 28 inches in the ground, From which;

A 16 inch fir bears S77W, 15.9 feet marked W1/16 S18 BT

A 12 inch fir bears N44W, 8.0 feet marked W1/16 S7 BT

T2S R36E S7 W1/16 S18 1980 OPLS 644

Brass washer nailed to B.T. blaze Used steel tape and magnetic compass with 20° East declination.
Measured to center of all B.T.s

REGISTERED PROFESSIONAL LAND SURVEYOR
Dund Light
OREGON JULY 10, 1964 DUANE I. GRIFFITH
634

State of				
for record on the day of		UNION COUNTY SURVEYOR		
(COUNTY OFFICIAL)	(DEPUTY)	JORVETOR		
m R6-7100-57 (9/71)		Date Received ☆ GPO798-276		
		Poto Filed		
		2.		
		F'e No. 248-84 R		