CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

In 1874, J. Hurlburt under G.L.O. Contract No. 201:

Set post 4 ft. long, 4 in. square, 2 ft. in ground for 1/4 sec. for.
Pine 10 in. dia. S 42°E 23 lks. Tamarack 6 in. dia. S61°W 16 lks.

	Index	File	No.	P-1	
	DIAGRAM T2S				
	2255			_	
	R35E	1	R36	E	
	24	+	1	9	
	1/4				
1		•			

Description of corner evidence found:

None.

Description of monument and accessories I established to perpetuate the original location of this corner:

Corner location determined by single proportionate measurement between the SW and NW corners of Section 19. At surveyed point set:

2 1/2"x30" galvanized pipe with brass cap attached 20" in the ground

stamped:

Dirt mound built to cap.

T2S R35E R36E 1/4

From which:

A 6" White Fir bears N63°E 8.3 ft. scribed

S19

1/4 S19 BT.

A 7" Doug. Fir bears N60°W 13.4 ft. scribed 1/4 S24 BT.

1981 OR PLS 1099

Attached 54-3 and 54-4 signs to BT's. Painted blazes and red 6" ring around BT's. Attached brass washer LS 1099 to foot blazes. Set metal fence post 5' north of corner with 54-4 sign.

The corner falls on NE slope 125' north of small clearing.

Compass Declination: 18 1/2° East.

I hereby certify the above described corner monument and/or accessories was established as described on Nov. 10, 1981.

Witnesses: Loren Huntsman Millard Wyatt

Office of Surveyor County of Union State of Oregon ... I hereby certify that the within instrument was filed in this office

HOWARD L. Perry by John Jones Congletion

UNION COUNTYSURVEYOR

REGISTERED **PROFESSIONAL**

AND SURVEYOR

OREGON

GARY L. LANGLITZ

1099

Date Received

Date Filed

Fle No. 283-84 R

Form R6-7100-57 (9/71)