History of original corner establishment:

Not previously established

Index File No. P-14

DIAGRAM T2S R36E <u>W 1/16</u> C-----C 22

Description of corner evidence found: None

Description of monument and accessories l established to perpetuate the original location of this corner:

Corner location determined by survey and subdivision of Section 22.

At surveyed point set 2 1/2"x30" galvanized pipe wth brass cap attached 14" in the ground stamped:

Built mound of stone and dirt to cap	W 1/16
from which:	C+C
A 15" Pond. Pine bears S69° 9.4 ft.	S22
scribed CW 1/16 S22 BT	1981
An 18" Doug. Fir bears N21°W 13.5 ft.	OR PLS 1981
scribed CW 1/16 S22 BT.	

Attached 54-3 and 54-4 signs to BT's. Painted blazes and 6" red ring around trees and attached brass washers LS 1099 to foot blazes. Set post 5' north of corner with 54-4 and 54-9 signs. Corner falls on east slope 30' south of power line and 110' east of dirt road.

Compass Declination: 18 1/2° East

I hereby certify the above described corner monument and/or accessories was established as described on November 23, 1981.



Fie No. 291-84 R

State of. Oregon	
for record on the 4 day of OCTRIBER 1982 Howard L. Perry by Low J.	UNION COUNTY SURVEYOR
Form R6-7100-57 (9/71)	Date Received
	D-th Filed
	Р _{.У}