


History of original corner establishment:  
Corner not previously established.



No record of subsequent monumentation found in Union County survey records.

Description of corner evidence found:

Corner not previously established

See map of survey dated November, 1989.

Description of monument and accessories I established to perpetuate the

original location of this corner: At position determined by survey, I set a 2 1/2" x 30" aluminum pipe with aluminum cap marked as shown, 26 inches in the ground, from which:

New Bearing Trees;

A 13 inch diameter Douglas Fir bears S18°W, 21.36 feet marked E1/16 S20 BT  
A 23 inch diameter Douglas Fir bears N65°W, 32.7 feet marked E1/16 S17 BT


Painted a 6 inch red band around all BTs and attached bearing tree and land survey monument signs.

Set a steel fencepost approximately 5 feet East with land survey monument and property boundary signs attached.

Raised a small mound of stone around monument.

I hereby certify that the above corner point was perpetuated as hereon described on October 19, 1989.

Witnesses: Rick Robinson and Jeff Petersen



REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON JULY 10, 1964  
DUANE I. GRIFFITH  
844

I used a steel tape and magnetic compass in the establishment of new accessories. I used 17° East magnetic declination and the distances are to a 50d spike driven in the right side of the root crown. I attached a brass washer marked OPLS 644 to the BT blaze.

Office of..... County of.....  
State of....., I hereby certify that the within instrument was filed in this office  
for record on the..... day of..... 19.....

UNION COUNTY SURVEYOR  
(COUNTY OFFICIAL)  
Date Received 12-27-89  
Date Filed 12-27-89  
By R. Robinson, Deputy  
File No. 253,891

(DEPUTY)

Form R6-7100-57 (9/71)

☆ U.S. GOVERNMENT PRINTING OFFICE - 1983-793-276