


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

P-19

History of original corner establishment:

Henry Meldrum surveyed the majority of the subdivision lines of Township 2 South, Range 37 East, W.M., under G.L.O. contract No. 450, dated June 11, 1882. There is no record of this corner being monumented.



Description of corner evidence found:

None.

Description of monument and accessories established to perpetuate the original location of this corner:

At the center quarter corner point as established by legal survey procedure, set 5/8" x 30" steel rebar 10" above ground with plastic cap mkd. HANLEY ENGR. PLS 1206. Set a steel fence post alongside.

From which: BT'S

- A 6" L.P. Pine bears N 27 E 23.7 ft. dist. mkd. C¼ S23 BT.
- A 9" L.P. Pine bears S 47 E 19.4 ft. dist. mkd. C¼ S23 BT.
- A 11" Doug Fir bears S 40 W 39.2 ft. dist. mkd. C¼ S23 BT.
- A 6" Doug Fir bears N 20 W 6.2 ft. dist. mkd. C¼ S23 BT.

Attached U.S.F.S. 54-9 signs and 54-3 tags to bearing trees.

I certify that the above monument was properly set under my direct supervision witnessed by Tom Fisk and Larry McBroom, October 23, 1989. The four bearing trees were scribed February 23, 1990, witnessed by Tom Fisk.

Office of..... County of.....
State of....., I hereby certify that the within instrument was filed in this office
for record on the..... day of....., 19.....

..... by
(COUNTY OFFICIAL)

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

James D. Hanley

OREGON
SEPTEMBER 23 1977
JAMES D. HANLEY
1206

**UNION COUNTY
SURVEYOR**

★ G.O.—798-276

Date Received 2-26-90

Date Filed 3-8-90

By R. ROBINSON DEPUTY

File No. 8-90R