


**CERTIFIED RECORD OF LAND CORNER MONUMENTATION**

**HISTORY OF ORIGINAL CORNER ESTABLISHED:**

None.

T 2 S R 37 E S-16



**DESCRIPTION OF CORNER EVIDENCE FOUND:**

None.

SEE SURVEY NUMBER 006-2019

**DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE ORIGINAL LOCATION OF THIS CORNER:**

At the position by survey I set a 5/8"x30" iron pin 24" in the ground with 2 1/2" aluminum cap marked as shown below, from which:

**NEW BEARING TREES:**

A 6" Douglas Fir bears North 83° East a dist. of 16.50 ft., marked NE 1/16 S27 BT.  
A 8" Douglas Fir bears South 17° East a dist. of 7.75 ft., marked NE 1/16 S27 BT.

Set steel fence post approx. 1 ft. South

Falls approx. 2 ft. South of seasonal stream on edge of timber.


I hereby certify that the corner was monumented on April 25, 2019.

Witness: Kyle A. Tucker.

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

OREGON  
June 2, 2010  
JEFFREY S. HSU  
83571

Renewal Date: June 30, 2019



**UNION COUNTY  
SURVEYOR**

Date Received 5/14/19

Date Filed 5/14/19

Filed By AGH

File Number 022-2019 R

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 13° East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing trees. The bearings are to a brass washer marked OPLS 83571 attached to the BT blaze of the new bearing trees.