


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

None.

T 2 S R 37 E T-15



DESCRIPTION OF CORNER EVIDENCE FOUND:

None.

SEE SURVEY NUMBER 006-2019

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE ORIGINAL LOCATION OF THIS CORNER:

At a position 25' West of a position determined by survey, I set a 5/8"x30" iron pin 8" drilled in rock, 14" in the ground with 2 1/2" aluminum cap marked as shown below, from which:

NEW BEARING OBJECTS:

- A 4' cliff face bears North 41° East a dist. of 2.55 ft., marked X BO.
- An 8'x6'x10' boulder with overhang bears South 50° East a dist. of 5.10 ft., marked X BO.
- A sloping 10'x5' boulder face bears South 53° West a dist. of 5.00 ft., marked X BO.
- A 5'x2'x3' rock outcrop bears North 46° West a dist. of 5.60 ft., marked X BO.

Set steel fence post approx. 6.45 ft. North 52° West.

Corner falls in a 30' cliff face. Witness corner is in the boulder patch to the West.


I hereby certify that the corner was monumented on April 25, 2019.

Witness: Kyle A. Tucker.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2019



**UNION COUNTY
SURVEYOR**

Date Received 5/14/19

Date Filed 5/14/19

Filed By N. L. G. Hsu

File Number 024-2019R

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 13° East declination, the distances and bearings are to the center of the chiseled 'X'.