


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:  
Corner not previously established.



No record of subsequent monumentation found in Union County survey records.

Description of corner evidence found:  
Corner not previously established  
See map of survey dated January, 1989.

**UNION COUNTY SURVEYOR**

---

Date Received 2-13-89  
Date Filed 2-13-89  
By G. LANGRISH, DEPUTY  
File No. 40-89 R

Description of monument and accessories I established to perpetuate the original location of this corner: At position determined by survey, I set a 2½" x 30" aluminum pipe with aluminum cap marked as shown, 27 inches in the ground, from which:


New BTs:  
A 10 inch diameter Douglas Fir bears S5°E, 30.1 feet marked X BT  
A 14 inch diameter Douglas Fir bears N80°W, 18.33 feet marked CE 1/16 S31 BT

Painted a 6 inch red band around all BTs and attached bearing tree and land survey monument signs.

Set a steel fencepost approximately 5 feet South with property boundary and land survey monument sign attached.

I hereby certify that the above corner point was perpetuated as hereon described on January 8, 1989.

Witnesses: Greg Blackman Sr. and Greg Blackman Jr.



**REGISTERED PROFESSIONAL LAND SURVEYOR**

OREGON  
JULY 10, 1964  
**DUANE I. GRIFFITH**  
644

I used a steel tape and magnetic compass in the establishment of new accessories. I used 17° East magnetic declination and the distances are to a 50d spike driven in the right side of the root crown. I attached a brass washer marked OPLS 644 to the BT blaze.

Office of..... County of.....  
State of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....  
..... by .....

(COUNTY OFFICIAL)

(DEPUTY)