CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established by Henry Meldrum under GLO Contract no. 450 dated June 11, 1882, and his record states:

Set basalt stone 19 x 18 x 6 x 18 ins in ground for 1/4 Sec. Cor. marked 1/4 on N face and raised a mound of stone alongside pits impracticable.

R-15	
DIAG	RAM
T 2 S	R 40 E
1 4	• <u>S 22</u> S 27
1989	
ORLS	1639

Description of corner evidence found:

None. Corner reestablished by proportionate measurement from survey control.

Corner search area is on very steep south slope strewn with rocks, boulders and rock outcrops - no trace of rock mound.

Description of monument and accessories I established to perpetuate the original location of this corner:

At position midway between adjacent section corners east and west...

Set a 2" x 30" aluminum pipe with $2\frac{1}{2}$ " aluminum cap 22" in ground & projecting 8" out of ground with surrounding stone mound & placed 6' steel fence post alongside with signs 54-2 & 54-9 attached. Cap marked as shown in corner diagram.

New bearing trees established: Ponderosa pine 27" dia brs $S80^{\circ}E$, 222.7' mkd 1/4 S27 BT. Ponderosa pine 15" dia brs $N42^{10}_{2}E$, 177.7' mkd 1/4 S22 BT.

New bearing trees have a brass washer marked PLS 1639 nailed flush to face of blaze. Attached signs 54-3 & 54-9 & painted face of blaze & a 6' band of red around each bearing tree.

Compass declination 190 East.

I hereby certify that the above described corner monument was properly established by me & witnessed by F.S. Munro on September 25, 1989.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William Z. Hanley

OREGOM
JULY 14, 1978
WILLIAM L. HANLEY
1639

Office of County Surveyor County of Uni	on	
for record on the day of by		
Form R6-7100-57 (9/71)	Date Received 3-12-96	•GPO591-971, 1 9 88

R-15.