


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

CORNER NOT SET IN ORIGINAL SURVEY by Rufus S. Moore in 1882



Description of corner evidence found:

Description of monument and accessories I established to perpetuate the original location of this corner: I set a 2 1/8" x 30" galvanized iron pipe with brass cap 16" in the ground and raised a mound of stone, at the corner position, from which BTs.;


A pine 10" in diameter bears N 48 E a distance of 24.0 feet, marked CE 1/16 S 16 BT

A fir 8" in diameter bears S 60 W a distance of 27.0 feet, marked CE 1/16 S 16 BT.

I placed a nail and a brass washer marked O.P.L.S. 991 at the BT. blaze.

I used a steel tape and a magnetic compass with 20 degrees East declination set into the compass.

I set a steel post with a sign 5.0 feet to the west of the corner.



REGISTERED PROFESSIONAL LAND SURVEYOR

Gregory T. Blackman

OREGON
JUL 3, 1973
GREGORY T. BLACKMAN
991

Office of Surveyor County of Union
State of Oregon I hereby certify that the within instrument was filed in this office
for record on the 18 day of Sept 1978
J. Voiles by G. L. Lyle
(COUNTY OFFICIAL) (DEPUTY)

UNION COUNTY SURVEYOR

Received _____

☆ GPO 799-509

Date Filed _____

By _____

File No. 415-84R