


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

D-21

History of original corner establishment:  
None. Corner was established as part of this survey.



Description of corner evidence found:

None.

Description of monument and accessories | established to perpetuate the original location of this corner:

At position established by survey:  
Set a 2½" X 30" aluminum pipe with a 2½" aluminum cap, buried 26" in the ground  
Attached signs 54-9 and 54-2 to 6' steel fence post set 4' East of monument.

New bearing trees established:  
A 13" ponderosa pine bears N 64 1/4° E - 62.8 ft., scribed "S 1/16 S1BT".  
A 22" ponderosa pine bears S 05° E - 27.1 ft., scribed "S 1/16 S1BT".

New bearing trees have a brass washer stamped "PLS 1106" nailed to face of blaze. Attached sign 54-3 & 54-9, painted face of blaze & a 6" red band around each bearing tree.

Bearing trees were tied using a Sokkia Automatic Total Station.

I hereby certify that the above corner monument was properly monumented to U.S.F.S. standards by me on November 10, 1994.

Compass declination 18° East.

Witnessed by: Greg E. Flowers, LSIT  
Todd Rosenbalm

REGISTERED PROFESSIONAL LAND SURVEYOR
---

*William R. Wells*

OREGON JULY 22, 1977 WILLIAM R. WELLS 1106
---

*renews 6/30/98*

Office of..... County of.....  
State of....., I hereby certify that the within instrument was filed in this office  
for record on the..... day of....., 19.....

..... by .....  
(COUNTY OFFICIAL)

Form R6-7100-57 (9/71)

<b>UNION COUNTY SURVEYOR</b>	
Date Received	<u>7-10-96</u>
Date Filed	<u>7-10-96</u>
By	<u>R. ROBINSON, DEPUTY</u>
File No.	<u>071-1996R</u>

★ BPO-798-276