


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner not previously established.



No record of subsequent monumentation found in Union County survey records.

Description of corner evidence found:

Corner not previously established.

See Union County Survey Number 25-89.

Description of monument and accessories I established to perpetuate the

original location of this corner: At position determined by survey, I set a 2½" x 30" aluminum pipe with aluminum cap marked as shown, 30 inches in the ground, from which:

New Bearing Trees;

- A 15 inch diameter Douglas Fir bears S20°W, 30.00 feet marked CE 1/16 S21 BT
- A 12 inch diameter Douglas Fir bears S78°W, 29.33 feet marked X BT

Raised a mound of stone around monument, 2 ft. base to top of cap.

Painted a 6 inch red band around all BTs and attached Bearing Tree and Land Survey Monument signs.

Set a steel fencepost approximately 5 feet North with Land Survey Monument sign attached.

I hereby certify that the above corner point was perpetuated as hereon described on September 29, 1989.

Witness: Jeff Peterson



REGISTERED PROFESSIONAL LAND SURVEYOR

Gregory T. Blackman

OREGON
JULY 13, 1973
GREGORY T. BLACKMAN
991

I used a steel tape and magnetic compass in the establishment of new accessories. I used 17° magnetic declination. The distances are to a 50d spike driven in the right side of the root crown. I attached a brass washer marked OPLS 991 to the BT blaze.

Office of..... County of.....
 State of..... I hereby certify that the within instrument was filed in this office
 for record on the..... day of.....

(COUNTY OFFICIAL)

(DEPUTY)

UNION COUNTY
by **SURVEYOR**

Date Received 11-14-89

Date Filed 11-14-89

By R. ROBINSON DEPUTY

File No. 220-89 e

Form R6-7100-57 (9/71)

*GPO-591-971, 1988