

CERTIFIED RECORD OF LAND CORNER MONUMENTATION


HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established

T 3 S R 38 E X-11

DESCRIPTION OF CORNER EVIDENCE FOUND:

None



See Survey Number 016-2018

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position determined by survey, I set a 2 ½" x 30" aluminum pipe with a 2 ½" aluminum cap marked as shown below, 22" in the ground with 2' diam. mound of stone from which:

NEW BEARING OBJECTS:

- A 7" Western Larch bears North 50° East, a distance of 19.85 feet, marked C 1/4 S33 BT.
- A 26" Douglas Fir bears South 13° East, a distance of 39.25 feet, marked C 1/4 S33 BT.
- A 14" Western Larch bears South 27° West, a distance of 30.35 feet, marked C 1/4 S33 BT.
- A 14" Western Larch bears North 27° West, a distance of 56.55 feet, marked C 1/4 S33 BT.

I set a steel fencepost approximately 1 foot East of monument.

I hereby certify that the corner was monumented on April 26, 2018.

Witness: Kyle Tucker

REGISTERED
PROFESSIONAL
LAND SURVEYOR



OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2019


UNION COUNTY
SURVEYOR

Date Received 5/29/18

Date Filed 5/29/18

Filed By Nil Gillman

File Number 016-2018R



I used a steel tape and magnetic compass in the establishment of the new accessories. I used 13° East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.