


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment/ Corner originally set in 1863 by David T. Thompson, under government contract number 103. Surveyor General notes state; "Set post for 1/4 section corner from which;" A pine, 12 inches in diameter bears S 30 W, 34 links dist. A pine 24 inches in diameter bears S 3 E 500 links dist. No. subsequent record of remonumentation in survey records.



Description of corner evidence found:

Found SW. bearing tree stump, decayed, and lower blaze visible.


Description of monument and accessories established to perpetuate the original location of this corner

Set a 1 1/2" x 36" galvanized pipe, with brass cap marked as shown, at the called bearing and distance from the S.W. bearing tree, from which New BT'S.
 A fir, 18 inches in diameter, bears S 75 E, 29.2 feet, marked 1/4 S 24 BT.

A pine, 20 inches in diameter, bears N 84 W, 9.2 feet, marked 1/4 S, 23 BT.

I used a steel tape and a magnetic compass with 20 degree East declination set into compass.

See survey number 46-79



REGISTERED PROFESSIONAL LAND SURVEYOR

Gregory T. Blackman
 OREGON
 JULY 13, 1973
 GREGORY T. BLACKMAN
 991

Office of County of
 State of , I hereby certify that the within instrument was filed in this office
 for record on the day of
 (COUNTY OFFICIAL) by (DEPUTY)

UNION COUNTY SURVEYOR
 Date Received 4-19-84
 Date Filed 4-19-84
 By G. LANGLITZ, DEPUTY
 File No. 846-84 R
GPO 796-333