


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:
Corner not previously established.



No record of monumentation found in UNION COUNTY survey records.

DESCRIPTION OF CORNER EVIDENCE FOUND:

Corner not previously established.

See Survey Number 027-1997.

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position determined by said survey, I set a 2 1/2" x 30" aluminum pipe with 2 1/2" aluminum cap marked as shown below, 20" in the ground, with mound of stone around monument, 1 ft. base to top of cap, from which:

NEW BEARING TREES:


A 11" Douglas Fir bears N 21°E, a distance of 7.36 ft, marked CW 1/16 S25 BT.
A 21" Ponderosa Pine bears S 31°E, a distance of 69.85 ft, marked CW 1/16 S25 BT.

I hereby certify that the corner was monumented on August 13, 1997.
Witnesses: Jeff Petersen, Jeff Madsen and Greg Blackman Jr.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1973
GREGORY T. BLACKMAN
991

Renewal Date: December, 31 1997



**UNION COUNTY
SURVEYOR**

Date Received 8-23-97

Date Filed 8-23-97

Filed By R. ROBINSON, DEPUTY

File Number 021-1997R

I used a steel tape and magnetic compass in the establishment of new accessories. The magnetic declination used was 18° East. The distances are to a 50d spike driven in the right side of the root crown. I attached a brass washer marked OPLS 991 to the bearing tree blaze.