CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: Corner has not been previously set.

DI AGRAH

T4S R35E

S1/16 S17 S16

1989 PLS 699

Description of corner evidence found: Corner is being set by this survey.

UMION COUNTY SURVEYOR

Dato Received 9-25-89

Dulo Filed 9-25-89

By G. LANGLITZ

File No. 189-89 R

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 2"x30" aluminum pipe with a 24" aluminum cap, marked as shown in the diagram, 6" in the ground to solid rock, at a point as determined by the procedures set forth in the MANUAL OF INSTRUCTIONS FOR THE SURVEY OF PUBLIC LANDS for the subdivision of sections. Built a mound of rock to be 36" in diameter by 20" high around the monument, from which new BTs are:

14" Ponderosa pine bears N12" 15'E, 252.9 feet scribed S1/16 S16 BT 13" Ponderosa pine bears N55°W, 212.3 feet scribed S1/16 S17 BT

Attached BT and Land Survey Monument signs to and painted a red band around each BT. Bearings were turned from the control traverse with a theodolite, basis of bearing being the bearing between the SE and S quarter corners of Section 7 as shown on MOS 43-76, to stamped brass washers nailed in the scribed red-painted blazes. Distances were measured from a 60d spike, with an aluminum washer stamped PLS 699, which was driven into the side of each BT approximately one foot above the ground. Set a steel fence post 5 feet N of the corner with a Land Survey Monument sign attached.

I, Leland L. Myers, P.O. Box 98, Sumpter, OR 97877, do hereby certify that on July 14, 1989, I established the corner as herein described.

REGISTERED PROFESSIONAL LAND SURVEYOR

> OREGON LELAND LEE MYERS

FILED

IN THE OFFICE OF THE Union COUNTY SURVEYOR
THIS ____ DAY OF

Union County Surveyor

USDA-FS Contract No. 04M3-8-6103

T4S R35E M-9