History of original corner establishment:

The original survey was by contract No. 452 dated June 16,

The original notes state; Set a basalt stone 14x8x6 ins. 9 ins in ground for corner to S 16,17,20 & 21 from which; A fir 30 in diam bears N8 E 20 lks dist marked T48. R36E in diam bears N8°E 20 1ks dist marked T48, R36E S 16 BT.

A fir 22" in diam bears S35°E 62 lks dist marked T4S R36E S21 BT.

A fir 14" in diam bears S40°W 48 lks dist marked T4S T36E S20 BT. A fir 24" in diam bears N8°W 13 lks dist marked T4S R36E S17 BT.

N-9				
DIAGRAM				
T4 S	R36EWM			
S17 S20	<u>516</u> 521			

Description of corner evidence found:

We could not find any evidence of corner other than bearing trees. Trees in Section 16 and 17 are standing with blaze scar. Tree in section 21 is a fallen log with scribe open for positive identification. Section 20 has a bearing tree standing with blaze scar.



File No. 485-84 R

Description of monument and accessories I established to perpetuate the original location of this corner

Set a 2" galvanized pipe 30" long with a bronze cap on top and a 8" plate welded to bottom. We set the pipe in a hole 22" deep and back filled with stone and tamped soil. A stone mounument was raised around pipe.

> COR T4S R36E I stamped the disk. 516 S20 S21 ORE LIC 381 1969

From the corner the original bearing trees are; A fir 28" in diam bears N8 W 13 lks dist.

A fir 36" in diam bears N8 E20 lks dist.

A down fir bears S35°E Approx 62 lks dist.

A fir 16" in diam bears \$50°W 40 lks dist. I also established a new bearing tree; A pine 26" in diam bears S74°E 60 ft. distance to center of the tree marked with scribe T4S R36E S21 BT. I placed a steel fence post with USFS sign 54-4 and National Forest Boundary sign indicating National forest land to south. USFS bearing tree signs were place on each of the bearing trees facing the corner.

Office of	A m. (alpha) RVEYOR
(COUNTY OFFICIAL)	Date Received
	Date Filed
	Ву

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Refer to Certified Record of Land Corner Monumentation 18-69A by James G. Voelz, PLS 381 as filed in the Office of the Union County Surveyor, July 23, 1969.

Index	File	No.	N-9	
DIAGRAM				
T4S		R	36E	
$\begin{array}{c c} 17 & 16 \\ \hline 20 & 21 \end{array}$				

Description of corner evidence found: Found: 2" Iron Pipe, firmly set extending 12" above ground, with brass cap attached, marked:

From which the original Government Survey BTs (Gradon, 1882):

An orig. 30" Fir, now a 46" Douglas Fir, alive, and well healed, bears ${\rm N8}^{\rm O}{\rm E}$ 13.2 ft.

An orig. 22" Fir, now down and rotted approx. 24" diam. with scribing "BT" visible on a rotten face, the root hole of which bears approx. $S23^{\circ}E$ 36.5 ft.

\$17 | \$16 \$20 | \$21 Ore. Lic. 381

COR

T4S R36E

1969

An orig. 14" Fir, now a 24" diam. Fir, alive, and well healed, bears $\rm S36^{0}W$ 31.7 ft. And an orig. 24" Fir, now a 30" Douglas Fir, alive and well healed bears $\rm N8^{0}W$ 8.6 ft.

A Bearing Tree established by Voelz, 1969. A 26" now 28" Ponderosa Pine, with scribing "4S R36E S21 BT" visible on an unhealed double blaze bears S74 $^{\circ}$ E 58.8 ft. (Rec. S74 $^{\circ}$ E 60 ft.)

Description of monument and accessories I established to perpetuate the original location of this corner:

Attached signs 54-4 to all BTs except original SE bearing tree.

Steel fence post with signs 54-2 and 54-4 attached is located approx. 3 ft. West of monument.

Compass Declination: 200 East.

Monument located approx. 15 ft. South of an E-W fence.

I hereby certify that the above described corner and/or accessories was visited on October 15, 1980.

Witness: John Curtiss

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 22, 1977
GARY L. LANGLITZ
1099

Date Filed

Office of County Surveyor C State of Oregon , I hereby certify that	ounty ofUnion the within instrument was filed in th	is office
for record on the day of by (COUNTY OFFICIAL)	, 19	UNION COUNTY
Form R6-7100-57 (9/71)		Date Received ☆ GPO—798-276