CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Original survey by General Land Office (Contract survey 1882)
The original notes read; Set a basalt stone 14x10x8 ins 9 ins
in ground for \$\frac{1}{4}Sec. cor. marked \$\frac{1}{4}\$ from which;
A pine 22" in diam bears N40°W 10 lks dist marked \$\frac{1}{4}SBT;
A pine 28" in diam bears S30°E 96 lks dist marked \$\frac{1}{4}SBT.;

N-19
diagram T4S R36Ewm
S14 S23

Description of corner evidence found:

Found- A pine 34" in diam bears S30°E 96 lks dist.
Found a stone mound but sould not identify the corner stone;

REGIETERED
ORFGON
LAND SOR YOR

MAY 4, 1956
JAMES G. VOELZ
381

Description of monument and accessories I established to perpetuate the

ariginal location of this come? AT the position of the corner I set a 2" galvanized pipe 30" long with bronze cap on top and 8" plate welded to bottom. The pipe was set to a depth of 14" and back filled with stone and soil and raised a stone monument.

I stamped the disk

tor T4s R36E

S14 S23 ORE LIC 381 1969

The original bearing trees from the monument are;

A pine 34" in diam bears S30°E 96 lks dist marked ‡SBT.

I set a new bearing tree; A pine 10" in diam bears N23°E 87.6

ft. dist marked ‡SBT. (distance measured to BT scribe on tree and tree marked with scribe) I set a steel fence post with USFS sign 54-4 attached. I placed a National Forest Boundary sign on the post indicating National Forest land to South. USFS bearing tree signs were placed on bearing trees shoulder high facing the corner.

Office of County Surveyor County of Oregon , I hereby certify that the with	Union	GURYEY OR
for record on the day of	and Date Re	red)
(COUNTY OFFICIAL)	Date File	
	Ву	101 01 0

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

T 45, R 36E., W.M.

History of original corner establishment:

This corner was originally established by Herman D. Gradon, U.S. Deputy Surveyor, under Contract No. 452, dated June 16, 1882. The original notes state that at the corner a 14 by 10 by 8 inch basalt stone, marked 1/4 on north face, was set 9 inches in the ground from which:

A pine 22 ins diam. bears N40°W 10 lks dist., marked 1/4 S. BI. A pine 28 ins diam. bears S30°E 96 lks dist., marked 1/4 S. BI.

In 1969, this corner was recovered and remonumented by LS 381. See recorded corner certificate No. 491-84R.

Corner Code No. N-19 Note: Monument marked as shown below

1/4 Cor T4S R36E <u>S14</u> S23 Ore Lic 381 1969

Compass Declination: 19.0° E

Description of corner evidence found:

Found a 3" brass cap on a 2 1/2" galv. iron pipe protruding 10" from a mound of stone from which:

A 26" ponderosa pine stump, 5' high, bears $$33^{\circ}$E 63.7'$ with scribes visible on a partly healed blaze. (Original bearing tree). A 18" ponderosa pine bears $$N23^{\circ}$E 88.0'$ with scribes visible on a partly healed double blaze. (Bearing tree by LS 381).

Description of monument and accessories I established to perpetuate the original location of this corner:

The monument was maintained by mounding with more earth and stone. Established one new bearing tree:

A 13" ponderosa pine bears S53 $1/2^{\circ}$ E 110.3' scribed 1/4 S23 BT.

New bearing tree has a brass washer stamped PLS 1106 nailed to face of blaze. Attached sign 54-3 and 54-9 and painted face of blaze and a 6" red band around each bearing tree. Set steel fence post east of corner and attached sign 54-9 and 54-2.

UNION COUNTY SURVEYOR
Date Received 1-5-89
Date Filed 1-6-89
By G. LANGLITE DEPUTY
File No. 3-89 R

PROFESSIONAL LAND SURVEYOR	
	1
Will-R. Well	0
JULY 22, 1977 WILLIAM R. WELLS	

1106

REGISTERED

Office of	County of
	, I hereby certify that the within instrument was filed in this office
	ay of , 19
	by
(COUNTY O	