


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Not established during original survey.

Index File No. P-2



Description of corner evidence found:

None.

Description of monument and accessories I established to perpetuate the original location of this corner:

Corner position established by survey and subdivision of Section 19. At surveyed point set 2½"x30" galvanized pipe with brass cap stamped: Set pipe 25" in ground with mound of dirt to cap.

T5S R36E

W1/16

C —+— C

S19

PLS 1099

1982

Bearing trees:

A Douglas Fir 6" dia. bears N58½°W, 8.1 Ft. scribed CW1/16 S19 BT

A Douglas Fir 8" dia. bears N72°E, 20.2 Ft. scribed CW1/16 S19 BT

Attached 54-2, 54-4 & 54-9 signs to metal post 6 Ft. North of corner.

Attached signs and painted trees per Standard Specification For Cadastral Surveys U.S.F.S. Region 6, Oct. 1979.

Corner falls on West slope 43 Ft. East of N-S fence.

Compass Declination: 19° East

I hereby certify the above described corner monument and/or accessories was established on August 20, 1982.

Witnesses: R. Orton
G. Wagoner
R. Scott

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

Gary L. Langlitz

OREGON
JULY 22, 1977
GARY L. LANGLITZ
1099

Office of..... Surveyor..... County of..... Union.....
State of..... Oregon.....

I hereby certify that the within instrument was filed in this office for record on the 4 day of OCTOBER, 1982

..... Howard L. Perry..... by Gary L. Langlitz.....
(COUNTY OFFICIAL) (DEPUTY)

**UNION COUNTY
SURVEYOR**

Date Received _____
☆ GPO—798-276

Date Filed _____

By _____

File No. 640-84R