


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. Q-1

History of original corner establishment:

Not established during original survey



Description of corner evidence found:

None

Description of monument and accessories established to perpetuate the original location of this corner:

Corner position established by survey & subdivision of section 19. At surveyed point set 2 1/4"x30" galvanized pipe with brass cap stamped:  
Set pipe 24" in ground.

No bearing trees available within 300'. Set 5/8"x30" rebar with yellow plastic cap marked "AP&A" bearing S58 1/2°W, 25.0 ft. Set 5/8" x 30" rebar with yellow plastic cap marked "AP&A" bearing S41°E, 25.0 ft.

Attached 54-3 & 54-4 signs to metal post next to rebar bearing objects. Attached 54-2 and 54-4 signs to metal post 6 ft. South of corner and 54-2 and 54-9 signs to metal post 6 ft. East of corner.

Corner falls on north slope 75' north of top of E-W knoll and 100' south of toe of knoll at meadow in old pole thicket now cut down.

Compass Declination: 19°E

I hereby certify the above described corner monument and/or accessories was established on August 20, 1982.

Witnesses: R. Orton  
G. Wagoner  
R. Scott

T5S  
S 1/16  
R35E | R36E  
24 + 19  
PLS 1099  
1982



Office of.....Surveyor..... County of.....Union.....  
State of.....Oregon....., I hereby certify that the within instrument was filed in this office  
for record on the...4... day of...OCTOBER....., 1982.  
.....Howard L. Perry..... by *Gary L. Langlitz*  
(COUNTY OFFICIAL) (DEPUTY)

<b>UNION COUNTY SURVEYOR</b>	
Date Received _____	
GPO 799-509	
Date Filed _____	
By _____	
File No. <u>643-84R</u>	