


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. Q-2

History of original corner establishment:

Not established during original survey.



Description of corner evidence found:

None.

Description of monument and accessories I established to perpetuate the original location of this corner:


Corner position established by survey and subdivision of Section 19. At surveyed point set 2 1/2"x30" galvanized pipe with brass cap stamped:

Set pipe 24" in ground with mound of dirt to cap.

Bearing Trees:

A Lodgepole Pine 6" dia. bears S7°E, 8.9 ft., scribed SW 1/16 S19 BT.

A Tamarack 9" dia. bears S88°W, 34.7 ft., scribed SW 1/16 S19 BT.



Attached signs and painted trees per Standard Specifications for Cadastral Surveys, USFS Region 6, Oct., 1979. Attached 54-2 and 54-4 signs on metal post 6 ft. west of cor. Attached 54-2 and 54-9 signs to metal post 6 ft. north of corner.

Corner falls on north slope 125 ft. south of bottom of draw course NW and 55' east of N-S fence.

Compass Declination: 19° E

I hereby certify the above described corner monument and/or accessories was established on August 20, 1982.

Witnesses: Rodger Orton
Glen Wagoner
R. Scott

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

Gary L. Langlitz
OREGON
JULY 22, 1977
GARY L. LANGLITZ
1099

Office of.....Surveyor..... County of.....Union.....
State of.....Oregon.....

I hereby certify that the within instrument was filed in this office
for record on the...4... day of...OCTOBER... 1982.

.....Howard L. Perry..... by *Gary L. Langlitz*.....
(COUNTY OFFICIAL) (DEPUTY)

**UNION COUNTY
SURVEYOR**

Date Received _____
Date Filed _____
By _____
File No. 644-84R

GPO 799-509