

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. R-3


History of original corner establishment:

Corner established in 1882 by H. Gradon, under General Land Office Contract No. 452.

Surveyor General's records state:

Set a post 3 feet long, 3 inches square, 24 inches in the ground, for 1/4 sec. cor., marked 1/4 S. on N. face from which:


- A Pine 16 inches diameter bears N20°E, 100 lks. distance, marked 1/4 S BT.
- A Pine 6 inches diameter bears S60°W, 24 lks distance, marked 1/4 S BT.



Description of corner evidence found:

A diligent search was made and no evidence could be found of the corner or its accessories.

Description of monument and accessories I established to perpetuate the original location of this corner: At surveyed point established by single proportion measurements set 2½" x 30" galvanized pipe with brass cap stamped:



Set pipe 24" in ground with no stones available for mound.

From which:

- A Western Larch 7" in dia. bears N9°W, 19.0 ft., scribed 1/4 S19 BT.
- A Douglas Fir 7" in dia. bears S45°W, 26.8 ft., scribed 1/4 S30 BT.

Attached 54-3 signs to both BTs. Attached brass washer stamped LS 1294 to foot blaze of both BTs. Painted blazes and 6" band around both BTs orange. Attached 54-4 signs to metal fence post 5' West of corner.



I hereby certify that the above corner monument was reestablished as herein described on November 2, 1979.

Witnesses: R. Orton
D. Allen

Office of..... County Surveyor..... County of..... Union
 Oregon
 State of....., I hereby certify that the within instrument was filed in this office
 for record on the..... day of....., 1979.

..... by
 (COUNTY OFFICIAL) (DEPUTY)

UNION COUNTY SURVEYOR	
Date Received	_____
Date Filed	_____
By	_____
File No.	647-84R