


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX FILE No. Y-9

History of original corner establishment:

None Set



Description of corner evidence found:

Description of monument and accessories established to perpetuate the original location of this corner: At surveyed point set 2½"x30" galvanized pipe with brass cap stamped: Set pipe 24" in ground. No stones available for mound.

From Which:

A Douglas Fir 7" in dia. bears N50°E, 26.5 ft., scribed S 1/16 S33BT.

A Douglas Fir 7" in dia. bears N46°W, 10.9 ft., scribed S 1/16 S32BT.

Attached 54-3 signs to both BT's. Attached brass washer stamped LS 1294 to foot blaze of both BT's. Painted blazes and 6" band around both BT's orange. Attached 54-2 and 54-9 signs to metal fence post 5' South of corner. Attached 54-2 and 54-4 signs to metal fence post 5' West of corner.

T5S R36 EWM  
S 1/16  
S32 + S33  
1979  
OR PLS 1294

I hereby certify the above corner monument was established as herein described.

October 25, 1979

WITNESSES: R. Orton  
D. Allen

**REGISTERED  
PROFESSIONAL  
LAND SURVEYOR**

OREGON  
SEPTEMBER 23, 1977  
**HOWARD L. PERRY**  
1 2 9 4

Office of.....County Surveyor..... County of..... Union.....

State of.....Oregon....., I hereby certify that the within instrument was filed in this office

for record on the..... day of....., 19 79

..... by  
(COUNTY OFFICIAL)

(DEPUTY)

Form R6-7100-57 (9/71)

**UNION COUNTY  
SURVEYOR**

---

Date Received \_\_\_\_\_  
GPO 799 509

Date Filed \_\_\_\_\_

By \_\_\_\_\_

File No. 671-84 R