

CERTIFIED RECORD OF LAND CORNER MONUMENTATION


2-8

History of original corner establishment:

Corner established in 1863 by Timothy W. Davenport under General Land Office Contract No. 102.

Surveyor General Record states:

Set post in mound of stone for corner on top of ridge



Retraced in 1881 by W.B. Barr under General Land Office Contract No. 388.

No record of subsequent remonumentation was found in County records.

Description of corner evidence found:

NONE

See map of survey dated June 1980.

Description of monument and accessories I established to perpetuate the original location of this corner:


At proportionate distance I set a 2½ inch x 30 inch iron pipe with brass cap marked as shown 22 inches in the ground from which;

NEW BT

A 13 in. dia. pine bears S12E, 164.8 feet marked ¼ S4 BT

A 3 foot x 3 foot x 1.5 foot rock outcrop bears N79W, 69.3 feet marked +80 on SE corner

Raised mound of stone 3½ foot base and 2 feet high.



REGISTERED
PROFESSIONAL
LAND SURVEYOR



OREGON
JULY 10, 1904
DUANE I. GRIFFITH
844

Brass washer nailed to B.T. blaze. Used steel tape and magnetic compass with 18° East declination. Measured to center of all B.T.s

Office of..... County of.....

State of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....

..... by (COUNTY OFFICIAL) (DEPUTY)

UNION COUNTY SURVEYOR

Date Received _____

Date Filed ★ 690-788-276

By _____

File No. 690-84R