


**CERTIFIED RECORD OF LAND CORNER MONUMENTATION**

**HISTORY OF ORIGINAL CORNER ESTABLISHED:**

Corner originally established by W. B. Barr under GLO contract number 388 dated May 7, 1881. Surveyor General field notes state:

- Set stake 4 ft. long, 4 in. diam. 18 in ground for corner to Secs. 2, 3, 10, and 11, from which:
- A Fir 4 in. diam. bears S10°E 20 lks. dist.
- A Fir 4 in. diam. bears N75°E 9 lks. dist.
- A Fir 3 in. diam. bears N50°W 5 lks. dist.
- A Tamarack 10 in. diam. bears S5°W 6 lks. dist.

T 5 S R 38 E E-17



**DESCRIPTION OF CORNER EVIDENCE FOUND:**

None found.

SEE SURVEY 035-2020

**DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE ORIGINAL LOCATION OF THIS CORNER:**

At proportionate position I set a 2 1/2" x 30" aluminum pipe, 26" in the ground, with 3" aluminum cap marked as shown below and in a 1.5' diam. mound of stone, From which:


**NEW BEARING OBJECTS:**

- A 5" Douglas Fir bears North 52° East a dist. of 11.65 ft., marked T5S R38E S2 BT.
- An 8" Western Larch bears South 1° East a dist. of 9.95 ft., marked T5S R38E S11 BT.
- A 9" Western Larch bears South 22° West a dist. of 13.00 ft., marked T5S R38E S10 BT.
- A 22" White Fir bears North 73° West a dist. of 9.20 ft., marked T5S R38E S3 BT.

A steel fence post bears North approx. 1'

I hereby certify that the corner was monumented on September 10, 2020.

Witness: Kyle A. Tucker



I used a steel tape and magnetic compass in the establishment of the new accessories. I used 14° East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR



OREGON  
June 2, 2010  
JEFFREY S. HSU  
83571

Renewal Date: June 30, 2021

**UNION COUNTY  
SURVEYOR**

Date Received 10/12/2020

Date Filed 10/12/2020

Filed By [Signature] DEPUTY

File Number 068-2020R