
## History of original corner establishment:

None



## Description of corner evidence found:

None

## Description of monument and accessories I established to perpetuate original location of this corner:

At the position determined by survey, I set a standard USFS  $2\frac{1}{2}$  ins. diam. by 30 ins. long alum. pipe, 26 ins. in ground, with  $3\frac{1}{4}$  ins. diam. alum. cap, and rock collar, with clear DEEP-1 magnet at base, mkd as shown:

From which:

A white fir, 18 ins. diam., bears N. 50° E., 38.1 ft. dist., mkd. C1/4 S32 BT. A ponderosa pine, 18 ins. diam., bears S. 83½° E., 66.7 ft. dist., mkd. C1/4 S32 BT. A tamarack, 21 ins. diam., bears S. 18½° W., 59.9 ft. dist., mkd. C1/4 S32 BT. A tamarack, 13 ins. diam., bears N. 8½° W., 75.7 ft. dist., mkd. C1/4 S32 BT.

Set guard post ±5 ft. SE'ly with Property Boundary (54-9) sign attached.

All new bearing trees are marked on a single blaze and have a nail with a brass washer stamped "LS 2648" right side center for distance measurements.

Painted 6 ins. red bands and added Bearing Tree (54-3) and Land Survey Monument (54-9) signs to all bearing trees.

Auto C/A geographic position: Lat. 45°05'10.1" N Long. 118°05'09.6" W

I hereby certify that the corner was monumented and accessories taken as described, using a Warren Knight staff compass, set with 15° East declination, and steel tape on August 14, 2014.

Witnesses: Kristina Powell, Brenda Johnson and Justin Seal



REGISTERED PROFESSIONAL LAND SURVEYOR

## Deceased

OREGON JANUARY 18, 1994 RON C. WALTER 2648

Renewal Date: June 30, 2016

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON
July 22, 1977
WILLIAM R. WELLS
1106

Renewal Date: June 30, 2016

UNION COUNTY SURVEYOR
Date Received 2 25/15
Date Filed 275/5
By AlGHun
File No. 043 2015R

**NOTE:** See "Explanation for Successor Certifying Surveyor" statement in Narrative of Record of Survey , CS 010-2015, filed concurrently with this Land Corner Record.