


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None



Description of corner evidence found:

None

Description of monument and accessories I established to perpetuate original location of this corner:

At the position determined by survey, I set a standard USFS 2½ ins. diam. by 30 ins. long alum. pipe, 25 ins. in ground, with ¾ ins. diam. alum. cap, and rock collar, with clear DEEP-1 magnet at base, mkd as shown:

From which:

- A ponderosa pine, 7 ins. diam., bears S. 71½° W., 40.5 ft. dist., mkd. XBT.
- A ponderosa pine, 12 ins. diam., bears N. 6½° W., 52.8 ft. dist., mkd. SE 1/16 S32 BT.

Set guard posts ±5 ft. E'ly with Property Boundary (54-2) sign and ±5 ft. N'ly with Property Boundary (54-2) and Land Survey Monument (54-9) signs attached.

All new bearing trees are marked on a single blaze and have a nail with a brass washer stamped "LS 2648" right side center for distance measurements.

Painted 6 ins. red bands and added Bearing Tree (54-3) and Land Survey Monument (54-9) signs as needed to all bearing trees.

Auto C/A geographic position:

Lat. 45°04'57.6" N
Long. 118°04'51.1" W

I hereby certify that the corner was monumented and accessories taken as described, using a Warren Knight staff compass, set with 15° East declination, and steel tape on August 14, 2014.

Witnesses: Kristina Powell, Brenda Johnson and Justin Seal



REGISTERED
PROFESSIONAL
LAND SURVEYOR

Deceased

OREGON
JANUARY 18, 1994
RON C. WALTER
2648

Renewal Date: June 30, 2016

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells

OREGON
July 22, 1977
WILLIAM R. WELLS
1106

Renewal Date: June 30, 2016

**UNION COUNTY
SURVEYOR**

Date Received 2/25/15

Date Filed 2/25/15

By *M. G. Albin*

File No. 046-2015R

NOTE: See "Explanation for Successor Certifying Surveyor" statement in Narrative of Record of Survey, CS 010-2015, filed concurrently with this Land Corner Record.