


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

This $\frac{1}{4}$ corner was set by deputy surveyor D. P. Thompson, under Contract No. 103, dated Sept. 3, 1863. He states he set a post for the $\frac{1}{4}$ sec. corner in a mound of stone.



Description of corner evidence found:

At the assumed $\frac{1}{4}$ corner location I found a raised mound of stone with a soft center where I assumed a post might have rotted away thus leaving a soft area.

Description of monument and accessories I established to perpetuate the original location of this corner:

With no other evidence available and the corner position appears correct by survey, I accepted the center of the mound of stone as being the true $\frac{1}{4}$ corner location. I then set an Alum. cap on a 2" x 30" pipe, with a magnet fixed in the cap, at the corner location. I buried the pipe to within 15" above the surface of very rocky ground. I then placed a mound of stone 4 feet dia. and 2 feet high about the pipe and covering the monument; from which the highest point on the north end of a large rock outcrop that is approximately 10 feet wide and 18 feet long and 5 feet high bears S 30 00 W, 11.0 feet. No bearing trees are available in the vicinity of this corner.

UNION COUNTY SURVEYOR

Date Received 9-22-87

Date Filed 9-25-87

by G. LANGLITZ, DEPUTY

File No. 133-87 R

REGISTERED PROFESSIONAL LAND SURVEYOR

James H. Hambleton

9-25-87

OREGON
JULY 10, 1964
JAMES H. HAMBLETON
645

REFER TO SURVEY 28-87

Office of..... County of.....
State of....., I hereby certify that the within instrument was filed in this office
for record on the..... day of....., 19.....
..... by
(COUNTY OFFICIAL) (DEPUTY)