CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner not previously established.

DIAG	RAM		
T5S	R41F	11	06
A 1861-1981 REVOLUTION	and the second second second second	angener in some er meneren ere	
		Ω	
	``	75	
to a copy water	and the same of the same of		
S			
A	top comment		

No record of subsequent monumentation found in Union County survey records

Description of corner evidence found:

Corner not previously established.

See map of survey number 038-1991

Description of monument and accessories I established to perpetuate the

original location of this corner: At position determined by survey , I set a $2\frac{1}{2}$ " x 30" aluminum pipe with aluminum cap marked as shown, 27 inches in the ground, from which:

New bearing trees: A 15 inch diameter Ponderosa Pine bears N24°W, 17.18 feet marked X RF A 12 inch diameter Ponderosa Pine bears N45°W, 16.73 feet marked SW1,16 S8 BT

Set a steel fencepost approximately 5 feet South with a Land Survey Monument sign attached.

I painted red bands around the hearing trees and attached land survey monument and bearing tree signs to the trees.

I raised a small mound of stone around cap.

I hereby certify that the above corner point was pestablished as hereon described on April 19, 1991.

Witness: Greg Blackman

REGISTERED
PROFESSIONAL
LAND SUNVEYOR

OREGON
JULY 10, 1964
DUANE 1. GRIFFITH
644

I used a steel tape and magnetic compass in the establishment of new corner accessories. I used 20° magnetic declination. The distances are to a 50d spike driven in the right side of the root crown. I attached a brass washer marked OPIS 644 to the BT blaze.

R.111

SW 1/16

1991 OPLS 644