

U. S. DEPARTMENT OF AGRICULTURE  
FOREST SERVICE

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 5-S R. 42-E Will Mer.

1/4 Corner common to Sections  
8, and 9

DESCRIPTION OF CORNER

Corner consists of a Not located

Dimension above ground \_\_\_\_\_ inches.  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

N	W	S	E

DIAGONAL POSITION

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	<u>1/4 S</u>		<u>1/4 S</u>
	<u>BT</u>		<u>BT</u>

Species \_\_\_\_\_  
Diameter 33"  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? Yes  
If not, why? \_\_\_\_\_

John R. Mitchell  
Signature  
10-25-41 Date  
Guard Title

100-52 (3/68)

EACH CORNER

4  
3  
2

USDA-FOREST SERVICE GPO 940-117  
Index File No. G-9  
T. 5-S R. 42-E  
Merid. \_\_\_\_\_  
CORNER DIAGRAM 1

CORNER RECORD (SEARCH)  
(Ref. FSM 7151.4)  
N. F. W-W R. D. Union  
State OR County Union  
Tract or Survey No. \_\_\_\_\_  
DESCRIBE CORNER MONUMENT FOUND \_\_\_\_\_  
Cor. No. \_\_\_\_\_

**UNION COUNTY SURVEYOR**

Date Received \_\_\_\_\_

Date Filed 12-28-87

By G. LANGLITZ, DEPUTY

File No. 451-87R

G-9