

R-1 LAND CORNER RECORD
(Rectangular)

5680-2

1. T 5 R 42E No. R-1 Cor. 114 Mer. 111 State OH N. F. 1 Dist. Union

2. Corner Status

④ 19

	<u>30</u>	

3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners: STONE 16X12X6
PP 16" N 5° E 42 LKS.
PP 12" S 30° E 88 LKS.

5. Investigation Notes: COULD NOT FIND STONE.
BOTH TREE'S AS DISCRIBED BY NOTES.
TREE TO NORTH ABOUT 22 DBH. COULD NOT
SEE SCRIBBING GROWN OVER, TREE TO
THE SOUTH 22 DBH. ABLE TO READ SCRIBBING
IN SCAT.

7. Photo Identification
Photo No. ENW-8-107
Ident. By: PIN PUNCHED

8. Plane Coordinate Position Data
State _____ Zone _____
X _____
Y _____
Etab. By _____
Field Book No. _____
Where Filed _____

9. Evaluation
Authentic _____
Needs Verif. _____ Monument _____
Re-estab. _____ Survey _____
Land Status _____

6. Signed A.R.C. Title Eng. Date 9/22/66

UNION COUNTY SURVEYOR

Date Received _____

Date Filed 12-28-87

By G. LANGLITZ, DEPUTY

File No. 456-87R

R-1

Dependent Resurvey of a Portion of the East Boundary,
T. 5 S., R. 41 E., Willamette Meridian, Oregon

CHAINS											
	<p style="text-align: center;">T 5 S R 41 E R 42 E ¼ S 25 1991</p> <p>from which new bearing trees</p> <p>A fir, 18 ins. diam., bears N. 59° W., 8 lks. dist., mkd. ¼ S25 BT.</p> <p>A ponderosa pine, 28 ins. diam., bears N. 31° W., 108 lks. dist., mkd. ¼ S25 BT.</p> <p>Deposit a white "DEEP-1" magnetic marker at the base and the corner stone alongside the stainless steel post.</p> <hr style="width: 20%; margin: auto;"/> <p>N. 1° 31' 30" E., beginning new measurement.</p> <p>Descend steep NE. slope, through moderate timber and light undergrowth.</p> <p>19.30 Bottom of steep descent; continue over gradual NE. slope.</p> <p>21.315 Point for the N 1/16 sec. cor. of sec. 25 only.</p> <p>Set a stainless steel post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.</p>										
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2" style="text-align: center;">UNION COUNTY SURVEYOR</td> </tr> <tr> <td style="width: 30%;">Date Received</td> <td style="text-align: center;">3/5/13</td> </tr> <tr> <td>Date Filed</td> <td style="text-align: center;">3/5/13</td> </tr> <tr> <td>By</td> <td style="text-align: center;"><i>N. L. G. Miller</i></td> </tr> <tr> <td>File No.</td> <td style="text-align: center;">182-2013R</td> </tr> </table>	UNION COUNTY SURVEYOR		Date Received	3/5/13	Date Filed	3/5/13	By	<i>N. L. G. Miller</i>	File No.	182-2013R	<p style="text-align: center;">N 1/16 S 25 1991</p> <p>from which</p> <p>A lodgepole pine, 10 ins. diam., bears S. 22° W., 34 lks. dist., mkd. N 1/16 S25 BT.</p> <p>A spruce, 13 ins. diam., bears S. 71½° W., 18 lks. dist., mkd. N 1/16 S25 BT.</p> <p>Set a steel fence post alongside the stainless steel post.</p>
UNION COUNTY SURVEYOR											
Date Received	3/5/13										
Date Filed	3/5/13										
By	<i>N. L. G. Miller</i>										
File No.	182-2013R										
<p>34.50</p> <p>35.90</p> <p>38.670</p>	<p>South Fork of Catherine Creek, 50 lks. wide, course N. 20° W.</p> <p>Dirt road, 25 lks. wide, bears NW. and SE.; asc. SW. slope.</p> <p>From this point, a point erroneously accepted as the cor. of secs. 24 and 25 only, by James Currin in 1898, bears East, 0.191 chs. dist., monumented with a basalt stone, 16 x 12 x 5 ins. (record, 16 x 10 x 5 ins.), loosely set at the center of the remains of an old stone mound with no marks. I mark the stone AM and bury it in place and scatter the remains of the old stone mound.</p>										
<p>40.470</p>	<p>From this point, the original closing cor. of secs. 19 and 30, T. 5 S., R. 42 E., bears East, 0.104 chs. dist., determined at record distance from the original bearing trees:</p> <p>A ponderosa pine, 30 ins. diam., bears N. 5° E., 42 lks. dist., with healed double blaze.</p>										

Dependent Resurvey of a Portion of the East Boundary,
T. 5 S., R. 41 E., Willamette Meridian, Oregon

CHAINS

A ponderosa pine, 30 ins. diam., bears S. 34° E., 88 lks. dist., with fragmentary scribe marks visible on opened upper blaze and with healed lower blaze. (Record, S. 30° E.)

At the corner point

Set a stainless steel post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, and in a collar of stone, with brass cap mkd.

T 5 S	T 5 S	
R 41 E	S 19	
		CC
S 25	S 30	
	R 42 E	
1991		

Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.

42.630

Point for the cor. of secs. 24 and 25 only, determined at Currin's record distance from the amended cor. of secs. 24 and 25 and on a line extended from said amended corner through the original closing cor. of secs. 19 and 30, T. 5 S., R. 42 E. These remaining physical monuments are regarded as the most reliable evidence of the former position of the unidentified monument called on line by Currin and now recognized as the true corner point. The displaced original corner stone, 14 x 8 x 5 ins., with illegible marks, bears N. 9° 00' 00" E., 0.178 chs. dist., lying loose.

Set a stainless steel post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, and in a mound of stone, 3 ft. base, to top, with brass cap mkd.

T 5 S	T 5 S	
S 24	R 42 E	
S 25	S 30	
R 41 E		
1991		

from which

A fir, 18 ins. diam., bears S. 79¼° W., 41 lks. dist., mkd. T5S R41E S25 BT.

A ponderosa pine, 12 ins. diam., bears N. 51° W., 22 lks. dist., mkd. T5S R41E S24 BT.

Deposit the displaced corner stone alongside and a white "DEEP-1" magnetic marker at the base of the stainless steel post.

From this point, the original closing cor. of secs. 19 and 30, T. 5 S., R. 42 E., bears S. 1° 14' 30" E., 2.160 chs. dist.

From this same point, the amended cor. of secs. 24 and 25 only, bears S. 1° 14' 30" E., 3.960 chs. dist.

N. 0° 30' 30" E., on the E. bdy. of sec. 24.

UNION COUNTY
SURVEYOR

Date Received 3/5/13

Date Filed 3/5/13

By AL Gilman

File No. 182-2013R