CERTIFIED RECORD OF LAND CORNER MONUMENTATION

U!	_ £				
History	ot	original	corner	establishme	ent:

Not set.

DIAGRAM	
T6S R38E	
C1/4—S8	

Description of corner evidence found:

None.

Description of monument and accessories I established to perpetuate the original location of this corner:

T6S R38E At surveyed point set 2 1/2" X 30" galvanized pipe and brass C1/4+S8 cap marked:

OR PLS 1051 Set pipe 24" in the ground and mound of stone around to cap. 1981 From which by magnetic declination of N20°E:

A 15" Pine, bears S82°W, 27.6 ft. scribed C 1/4 S8 BT.
A 12" Pine, bears N27°W, 58.0 ft. scribed C 1/4 S8 BT.
Painted blazes red and 6" red band around. Placed 54-3s and brass washers

stamped PLS 1051 on the BTs. Placed Crown Zellerbach property sign and 54-9 on a steel fence post 5' West of the corner. Corner falls about 20' East of a north-south fence line.

> I hereby certify that the above corner monument was established as herein described.

Witnesses: Daniel Rowland Douglas Moser Beverly Weaselhead

May 13, 1981

	The state of the s
	PROFESSIONAL
0	LAND SURVEYOR
130	THE TANK IN
	OREGON OCT. 17, 1975 BARRY B. BARBOUR

Office of County Surveyor County of Union	
State of	UNION CONTY
Form R6-7100-57 (9/71)	Date Received
	Date Filed
	By
	File Na. 784-84R