

History of original corner establishment:



Description of corner evidence found:

Description of monument and accessories I established to perpetuate the original location of this corner:



File No. 148-1998 R

Set a USFS 3 1/4" aluminum capped pipe, 28" in ground with small mound of stones to cap. 5' ± Easterly man made creek, 15' ± southerly of creek.


A Fir, 17" diam., bears N.78°20'W., 30.3', scribed "N1/16S11BT". A Fir, 16" diam., bears N.02°15'W., 5.5, scribed "N1/16S12BT".

REFERENCE: RECORD OF SURVEY, LONGSHOT CADASTRAL SURVEY WITNESS TO MONUMENT: ERIC GREEN BEARINGS TAKEN TO BRASS TAG AT CENTER OF BLAZE, DISTANCES MEASURED TO BRASS TAG ON SIDE CENTER OF TREE. OBSERVED WITH ELECTRONIC TOTAL STATION AND STEEL TAPE.
BASIS OF BEARINGS WAS A GEODETIC BEARING DETERMINED FROM GPS OBSERVATIONS.

		ATTENDED TO SEE AN ADDRESS OF ADDRESS OF ADDRESS OF A DESCRIPTION OF A DES
Office of	County of	minal county
State of I hereby	certify that the within instrument was	s filed in this office
for record on the day of	by	Date Received 10/28/98
(COUNTY OFFICIAL)	(DEPUTY)	Date Filed 10/31/98
		By R. ROBINSON DEPUTY

AP

History of original corner establishment:




Description of corner evidence found:


Description of monument and accessories I established to perpetuate the original location of this corner:

Set a USFS 3 $\frac{1}{4}$ " aluminum capped pipe, cap marked per diagram, 28" in ground with small mound of stones to cap. S. \pm Easterly man made creek, 15' \pm southerly creek.

A Fir, 28" diam., bears N.77°29'E., 25.8', scribed "N1/16S12BT". A Fir, 24" diam., bears N.36°39'W., 7.9', scribed "N1/16S11BT".

REFERENCE: RECORD OF SURVEY, LONGSHOT CADASTRAL SURVEY WITNESS TO MONUMENT: ERIC GREEN BEARINGS TAKEN TO BRASS TAG AT CENTER OF BLAZE, DISTANCES MEASURED TO BRASS TAG ON SIDE CENTER OF TREE. OBSERVED WITH ELECTRONIC TOTAL STATION AND STEEL TAPE. BASIS OF BEARING WAS GEODETIC BEARING DETERMINED FROM GPS OBSERVATIONS.





Office of	County of	W 3	 State of the state of the state
State of I herel	y certify that the wi	thin instrun	ent was filed in this office
for record on the day of	, 20	•	
]	Ву	•	
(COUNTY OFFICIAL)	(DEPUTY)		
AP			

History of original corner establishment:

Corner originally established in 1994 by Ronald E. Stoll, PLS 2058, under U.S. Forest Service contract. Stoll's notes state:

Set USFS 3 1/4" aluminum capped pipe, cap marked per diagram, 28" in ground with small mound of stone to cap. S +/- Easterly man made creek, 15' +/- southerly creek.

A Fir, 28" diam., bears N77*29'E, 25.8', scribed: N1/16 S12 BT. A Fir, 24" diam., bears N36*39'W, 7.9', scribed: N1/16 S11 BT.

F-21

DIAGRAM

T6S R41E

N 1/16

S11 S12

LS 2058

1994

Typical USFS Cap

Description of corner evidence found:

A 3 1/4" USFS aluminum cap on aluminum pipe marked as shown in corner diagram 2" above ground in small stone mound.

From Which:

A Douglas Fir 22" in diameter bears N77°W (Record N77°29'E), 30.4' (Record 25.8') with visible scribing.

A Douglas Fir 20" in diameter bears N2°W (Record N36°39'W), 5.7' (Record 7.9') with visible scribing.

Steel fencepost with 54-2 and 54-9 signs bears east, 1.4'. Steel fencepost with 54-2 sign bears south 2.9'.

Wisdom Creek is +/- 30' to north. Steel channel with diversion from Wisdom Creek running into it from the east is +/- 50' to south.

Description of monument and accessories I established to perpetuate the original location of this corner:

Corner monument evidently moved by Stoll after bearing trees were taken. Bearing tree scribes and chaining nails do not face corner monument. Install new 40d spikes in right side center of both bearing trees. Remeasure bearings and distances to both bearing trees. Both bearing trees are in Section 11.

Bearing trees have 54-3 and 54-9 signs and have a 6" red painted band.

Date: November 21, 2007

Declination: 16°E

UNION COUNTY SURVEYOR

Date Received 12/1/107

Date Filed 12/1/107


10. 028-2007/2

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON
JULY 19, 1994
KENNETH A. LIND

Renews: 12-31-08

History of original corner establishment:




Description of corner evidence found:


Description of monument and accessories I established to perpetuate the original location of this corner:

Set a USFS 3 $\frac{1}{4}$ " aluminum capped pipe, cap marked per diagram, 28" in ground with small mound of stones to cap. S. \pm Easterly man made creek, 15' \pm southerly creek.

A Fir, 28" diam., bears N.77°29'E., 25.8', scribed "N1/16S12BT". A Fir, 24" diam., bears N.36°39'W., 7.9', scribed "N1/16S11BT".

REFERENCE: RECORD OF SURVEY, LONGSHOT CADASTRAL SURVEY WITNESS TO MONUMENT: ERIC GREEN BEARINGS TAKEN TO BRASS TAG AT CENTER OF BLAZE, DISTANCES MEASURED TO BRASS TAG ON SIDE CENTER OF TREE. OBSERVED WITH ELECTRONIC TOTAL STATION AND STEEL TAPE. BASIS OF BEARING WAS GEODETIC BEARING DETERMINED FROM GPS OBSERVATIONS.





Office of	County of	и 4	A State of the Sta
State of I herel	y certify that the wi	ithin instrum	ent was filed in this office
for record on the day of	, 20	•	
]	Ву	•	
(COUNTY OFFICIAL)	(DEPUTY)		
AP			

History of original corner establishment:

Corner originally established in 1994 by Ronald E. Stoll, PLS 2058, under U.S. Forest Service contract. Stoll's notes state:

Set USFS 3 1/4" aluminum capped pipe, cap marked per diagram, 28" in ground with small mound of stone to cap. S +/- Easterly man made creek, 15' +/- southerly creek.

A Fir, 28" diam., bears N77*29'E, 25.8', scribed: N1/16 S12 BT. A Fir, 24" diam., bears N36*39'W, 7.9', scribed: N1/16 S11 BT.

F-21

DIAGRAM

T6S R41E

N 1/16

S11 S12

LS 2058

1994

Typical USFS Cap

Description of corner evidence found:

A 3 1/4" USFS aluminum cap on aluminum pipe marked as shown in corner diagram 2" above ground in small stone mound.

From Which:

A Douglas Fir 22" in diameter bears N77°W (Record N77°29'E), 30.4' (Record 25.8') with visible scribing.

A Douglas Fir 20" in diameter bears N2°W (Record N36°39'W), 5.7' (Record 7.9') with visible scribing.

Steel fencepost with 54-2 and 54-9 signs bears east, 1.4'. Steel fencepost with 54-2 sign bears south 2.9'.

Wisdom Creek is +/- 30' to north. Steel channel with diversion from Wisdom Creek running into it from the east is +/- 50' to south.

Description of monument and accessories I established to perpetuate the original location of this corner:

Corner monument evidently moved by Stoll after bearing trees were taken. Bearing tree scribes and chaining nails do not face corner monument. Install new 40d spikes in right side center of both bearing trees. Remeasure bearings and distances to both bearing trees. Both bearing trees are in Section 11.

Bearing trees have 54-3 and 54-9 signs and have a 6" red painted band.

Date: November 21, 2007

Declination: 16°E

UNION COUNTY
SURVEYOR

Date Received 12/1/17

Date Filed 12/1/17

13. 028-2007/2

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON
JULY 19, 1994
KENNETH A. LIND

Renews: 12-31-08