


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

0-1

History of original corner establishment:
None.



See Survey 052-1944
Description of corner evidence found:

None.

Description of monument and accessories I established to perpetuate the original location of this corner:

At postion established by survey:

Set a 2½" X 30" aluminum pipe with a 2½" aluminum cap, 26" in ground and surrounded with a mound of earth and stone.

Attached sign 54-9 to steel fence post, set 3.4 feet East of monument.
Set a steel fence posts 7.6 feet South and N45°W-3.0 feet from the monument.

New bearing trees and objects established:

A 11" ponderosa pine bears S 13° E -271.7 feet, scribed: N1/16S19BT.
A 5/8" X 30" rebar with a 1½" aluminum cap stamped "RM N1/16 S19-19.5FT.
1106" bears N 20° E - 19.5 feet. Attached sign 54-3 & 54-9 to steel fence post which bears N20°E-1.8 feet from the reference monument.

New bearing trees have a brass washer stamped "PLS 1106" nailed to face of blaze. Attached sign 54-3 & 54-9, painted face of blaze & a 6" red band around each bearing tree.

I hereby certify that the above corner monument was properly monumented to U.S.F.S standards by me on December 23, 1993.

Compass declination 18° East.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

Renews 12-31-94

Office of..... County of.....
State of..... I hereby certify that the within instrument was filed in this office
for record on the..... day of.....

(COUNTY OFFICIAL

(DEPUTY)

UNION COUNTY	
SURVEYOR	
Date Received	<i>11/3/94</i>
Date Filed	<i>11/14/94</i>
By	<i>Gregory T. Black</i>
File No	<i>156-1994R</i>