


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:
None.



See Survey 052-1994
Description of corner evidence found:

None.

Description of monument and accessories | established to perpetuate the original location of this corner:

At postion established by survey:

Set a 2½" X 30" aluminum pipe with a 2½" aluminum cap, 27" in ground and surrounded with a mound of earth and stone.

Attached sign 54-9 to steel fence post, set 3.0 feet East of monument.

New bearing trees established:

A 20" ponderosa pine bears S 18½° W - 29.5 feet, scribed: CN1/16S19BT.

A 15" ponderosa pine bears S 80° E - 9.7 feet, scribed: CN1/16S19BT.

New bearing trees have a brass washer stamped "PLS 1106" nailed to face of blaze. Attached sign 54-3 & 54-9, painted face of blaze & a 6" red band around each bearing tree.

I hereby certify that the above corner monument was properly monumented to U.S.F.S standards by me on December 29, 1993.

Compass declination 18° East.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

RENEWS 12-31-94

Office of..... County of.....
State of....., I hereby certify that the within instrument was filed in this office
for record on the..... day of.....

(COUNTY OFFICIAL)

(DEPUTY)

**UNION COUNTY
SURVEYOR**

Date Received 11/3/94

Date Filed 11/14/94

By *Gregory T. Clark*

File No 157-1994R