


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

R-2

History of original corner establishment:

None.



See Survey 052-1994
Description of corner evidence found:

None.

Description of monument and accessories I established to perpetuate the original location of this corner:

At postion established by survey:

Set a 2½" X 30" aluminum pipe with a 2½" aluminum cap, 20" in ground and surrounded with a mound of earth and stone.

Attached sign 54-9 & 54-2 to steel fence post, set 4.0 feet North of monument.

New bearing objects established:

A 5/8"X 30" rebar with a 1½" aluminum cap stamped "RM W1/16 S19-21.6 Ft 1106" bears N17°E-21.6 feet with a steel fence post and sign 54-9.

A 5/8"X 30" rebar with a 1½" aluminum cap stamped "RM W1/16 S30-20.1 Ft 1106" bears S66°E-20.1 feet with a steel fence post and sign 54-9.

I hereby certify that the above corner monument was properly monumented to U.S.F.S standards by me on December 9, 1993.

Compass declination 18° East.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

renews 12-31-94

Office of..... County of.....
State of....., I hereby certify that the within instrument was filed in this office
for record on the..... day of.....

(COUNTY OFFICIAL)

(DEPUTY)

UNION COUNTY SURVEYOR	
Date Received	<u>11/3/94</u>
Date Filed	<u>11/14/94</u>
By	<u><i>Gregory T. Clark</i></u>
File No	<u>162-1994K</u>

Form R6-7100-57 (9/71)

*GPO-691-971, 1988