

## BASIS of BEARING

The recorded bearing from the West 1/4 corner of Section 35 to the NW corner of Section 35 as shown on map of survey number 31-80, as filed in the office of the Union County Surveyor.

## NARRATIVE

This survey was made at the request of Boise Cascade
Corporation to locate and establish the C-W I/I6 and the West I/I6
corners in Section 35 as shown hereon. I based on Surveys 31-80 and
4-80 as noted. I broke the section in the standard manner as set
forth in the BLM Manual. I found no unusual conditions.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 10, 1964

DUANE I. GRIFFITH
644

Map of Survey number 31-80 as filed in the office of the Union County Surveyor

Map of Survey number 4-81 as filed in the office of the Union County Surveyor

- Found brass cap monument as shown on map of survey 31-80.
- Found brass cap monument as shown on map of survey 4-81.
- Set 2-1/2" X 30" aluminum monument as described in monumentation records filed separately.
- ) Record bearing and distance, map of survey 31-80.
- 1 Record bearing and distance, map of survey 4-81.

UPSION COUNTY
SURVEY DR

Data Filed 9/16/9/

By Live Black

File No. 05/- 1991

## BAGETT-GRIFFITH & ASSOCIATES LaGrande, Oregon Map of Survey

Establish I/16 corners in Section 35, T 4 N, R 39 E, WM.

UNION COUNTY, OREGON

SURVEYED FOR BOISE CASCADE CORPORATION

SURVEYED BY dig IPP Sept. 1991

Scale: I' = 500' Drawn by: lugy Sept. 1991

4. .