## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: None.

L.75-3					
CHARGOSTON	DIAGRAM T 6 S R 42 E				
	C     S-N-S				
	1/256 <b> </b> C				
	1993				
- Chromosom	PLS 1106				

See Survey 052-1997
Description of corner evidence found:

None.

Description of monument and accessories I established to perpetuate the original location of this corner:

At postion established by survey:

Set a  $2\frac{1}{2}$ " X 30" aluminum pipe with a  $2\frac{1}{2}$ " aluminum cap, 22" in ground and surrounded with a mound of earth and stone.

Attached signs 54-2 & 54-9 to steel fence post, set 3.3 feet East of monument.

A 6' steel fence post bears West 3.4 feet.

New bearing trees established: A 23" douglas fir bears N  $57\frac{1}{2}$ °E - 29.3 feet, scribed: S-N-S1/256S18BT. A 14" ponderosa pine bears S  $8\frac{1}{2}$ ° E - 32.4 feet, scribed:

New bearing trees have a brass washer stamped "PLS 1106" nailed to face of blaze. Attached sign 54-3 & 54-9, painted face of blaze & a 6" red band around each bearing tree.

I hereby certify that the above corner monument was properly monumented to U.S.F.S standards by me on December 14, 1993.

Compass declination 18° East.

S-N-S1/256S18BT.

Office of	County of	WILLIAM R. WELLS
State of, / herel	by certify that the within instrument was filed	d in this office enews 12-31-94
for record on the day of	nusion c <sub>18</sub> acity	
(COUNTY OFFICIAL)	(DEPUTY)	
Form R6-7100-57 (9/71)	Data Paraived 11/3/94	*GPO-591-971, 1988
	5 to 51ed 11/14/94	

File No. 148-1994 R

Natta The Drewn. 1/22

PROFESSIOMAL

LAND SU VEYER

## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: None.

DIAGRAM T 6 S R 42 E S 18 C-S-N-SE 1/2561993 PLS 1106

See Surrey 052-1994

Description of corner evidence found:

None.

Description of monument and accessories I established to perpetuate the original location of this corner:

At postion established by survey:

Set a  $2\frac{1}{2}$ " X 30" aluminum pipe with a  $2\frac{1}{2}$ " aluminum cap, 26" in ground and surrounded with a mound of earth and stone.

Attached signs 54-2 & 54-9 to steel fence post, set 3.2 feet North of monument.

New bearing trees established: A 38" douglas fir bears N 72° E - 16.2 feet, scribed: C-S-N-SE1/256S18BT. A 12" ponderosa pine bears S 36° W - 11.0 feet, scribed: C-S-N-SE1/256S18BT. The point of a rock bluff bears N 38° E - 27.0 feet. New bearing trees have a brass washer stamped "PLS 1106" nailed to face of blaze. Attached sign 54-3 & 54-9, painted face of blaze & a 6" red band around each bearing tree.

I hereby certify that the above corner monument was properly monumented to U.S.F.S standards by me on December 14, 1993.

Compass declination 18° East.

WILLIAM R. WELLS

•GPO-591-971, 1988

PROF ST P

rice of County of		1106	
State of   hereby cert	ify that the within instrument was filed in this office	renows 12 - 71 91	
for record on the day of	by (DEPUTY)	.,	
(COUNTY OFFICIAL)	(DEPUTY)		

Form R6-7100-57 (9/71)

Data Received 11/3/84

Data Rich 11/14/84

By Llyg 1. Black

File No 149-1994R

See varieties Orang 1/22