A-3

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

(T2S R38E)

DIAGRAM

T 1 S R 38 E

$\frac{1}{4}$ $\frac{S\ 31}{S\ 6}$

T 2 S

History of original corner establishment:

Corner established by T. W. Davenport under GLO contract no 102 dated July 20, 1863.

Surveyor General records state:

Set qr. sec post from which:

A white fir 12 ins diam bears S 30° W, 56 lks.
A red fir 6 ins diam bears N 20° W, 34 lks.

Description of corner evidence found:

NONE: Corner is reestablished at single proportionate distance between the found Northwest and Northeast corners of Section 6.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 2½ inch brass cap on a 2 inch galvanized iron pipe 31 inches long 26 inches in the ground with 5 inches projecting out of the ground with a large surrounding rock mound and a 6 foot steel fence post alongside with a sign 54-4 attached.

Brass cap marked thus:

T 1 S R 38 E

$\frac{1}{4}$ $\frac{S\ 31}{S\ 6}$

T 2 S

1983

ORLS 1639

New bearing trees:

A spruce 14 ins diam bears N 05° E, 25.6 feet dist marked 1/4 S 31 BT.
A spruce 11 ins diam bears S 52° W, 15.2 feet dist marked 1/4 S 6 BT.

Each new bearing tree has a sign 54-3 nailed below a 6 inch band of red paint and a brass washer marked PLS 1639 nailed flush with BT blaze with a sign 54-4 nailed on opposite side of tree from BT blaze.

I hereby certify that the above described corner was properly established by me on Aug. 23, 1983, and witnessed by Jim DeMastus and Tom Fisk.

REGISTERED PROFESSIONAL LAND SURVEYOR

William L. Hanley

OREGON
JULY 14, 1978
WILLIAM L. HANLEY
1639

Office of County Surveyor *County of* Union
State of Oregon, *I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....*
..... *by* .....
(COUNTY OFFICIAL) (DEPUTY)

UNION COUNTY SURVEYOR

Date Received 9-6-83
☆ GPO 798-276
Date Filed 9-12-83
By G. LANGLITZ DEPUTY
File No. 338-83 R

Form R6-7100-57 (9/71)