CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner was established in 1882 by Henery Meldrum, Deputy Surveyor under Contract No. 450. Surveyor General's records state: Set a basalt stone $16 \times 8 \times 6$, 11" in ground, $\frac{1}{4}$ mkd. on west face and a raised mound of stone along side.

R 40 E S 10 1980 ORLS 645

Description of corner evidence found:

At assumed corner location, I found a stone filling the GLO dimensions, though I could not find any markings. Also I found a mound of stone with a rock jack along side and evidence of a fence line to the west. After evaluating this evidence, I determined this to be the $\frac{1}{4}$ cor. location.

Description of monument and accessories I established to perpetuate the original location of this corner

I set a 2" galv. iron pipe, 30" long with a brass cap, 18" above surface, in a large mound of stone, with cap stamped as shown above.

I set two bearing trees:
A 9" pine bears S 26 W, 67.0 feet and scribed \(\frac{1}{4}\) S BT.
A 10" fir bears S 47 E, 4.85 feet and scribed \(\frac{1}{4}\) S BT.

REGISTERED **PROFESSIONAL** LAND SURVEYOR

5-20-80

est No

OREGON JULY 10, 1964 JAMES H. HAMBLETON

State of....... , I hereby certify that the within instrument was filed in this office for record on the day of (COUNTY OFFICIAL)

Form R6-7100-57 (9/71)

| UNION COUNTY SURVEYOR |
|--------------------------|
| Date Received |
| Date Filed SPO 795 222 |
| Ву |
| File No. 149-84R |