CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:
No previous history.

G-20
DIAGRAM

T 1 S R 40 E
E-C- 1/16
S 11
1979
ORLS 645

Description of corner evidence found:

None

Description of monument and accessories I established to perpetuate the original location of this corner

I set a l'galv. iron pipe with brass cap approx. 6" above surface of ground. No stone available so did not place any stone about the monument. Cap stamped as shown above.

Set two bearing trees: A 9" D. fir bears N 20 E, 14.10 ft. and scribed 1/16 S BT.

A 12" P. pine bears S 61 E, 28.0 ft. scribed 1/16 S BT.

PROFESSIONAL LAND SURVEYOR

OREGON
JULY 10. 134

JAMES H. HAMBLETON
645

Office of	
Office of	County of
State of	mad Albana a dalaba a mana
(COUNTY OFFICIAL)	(DEPUTY)

Form R6-7100-57 (9/71)

UNION COUNTY SURVEYOR	
Date Received	
Date Filed	
Ву	
File No. 155-84R	

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

No previous history.

G-20

DIAGRAM

T 1 S R 40 E E-C- 1/16 1979 ORLS 645

Description of corner evidence found:

None

Description of monument and accessories I established to perpetuate the original location of this corner

I set a 1" galv. iron pipe with brass cap approx. 6" above surface of ground. No stone available so did not place any stone about the monument. Cap stamped as shown

Set two bearing trees:
A 9" D. fir bears N 20 E, 14.10 ft. and scribed 1/16 S BT.

A 12" P. pine bears S 61 E, 28.0 ft. scribed 1/16 S BT. S66 15E 27.94

Note:

Distance and bearing to bearing trees

is amended 5-20-80

Tames Af Hamblus

REGISTERED **PROFESSIONAL** LAND SURVEYOR

OREGON JAMES H. HAMBLETON 645

State of......, I hereby certify that the within instrument was filed in this office

Form R6-7100-57 (9/71)

UNION COUNTY **SURVEYOR**

Date Received

☆ GPO 796-333

File No. 156-84 R

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner originally established by James H. Hambleton as per Union County Survey Number 32-80. Union County galv. iron Monumentation Record 156-84R states: Set a 1" pipe with brass cap approx. 6" above surface of ground. No stone available so did not place any stone about the monument. Cap stamped as shown.

Set two new bearing trees:
A 9" Douglas Fir bears N 18 E, 15.73 ft. scribed 1/16 S BT. A 12" Ponderosa Pine bears S 66 15 E, 27.94 ft. scribed 1/16 S BT.

T1S R40 EG-20 S 11

DESCRIPTION OF CORNER EVIDENCE FOUND:

Found 1 1/2" iron pipe, 8" above ground, with 2 1/2" brass cap marked as shown below, and under a tripod of fence posts, from which:

A 16" Douglas Fir bears North 16° East a dist. of 15.70 ft., alive and vigorous with healed

An 18" Ponderosa Pine stump bears South 66° East a dist. of 28.00 ft., dead and rotten with BT scribe visible on reverse face upon excavation.

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATED THE ORIGINAL LOCATION OF THIS CORNER:

From the Iron Pipe,


NEW BEARING OBJECTS:

An 8 " Douglas Fir bears North 74° West, a dist. of 22.70 ft., marked CE 1/16 S11 BT.

Fence corner to North/East/West bearing fence lines falls Northeasterly approx. 8 ft.

I hereby certify that the corner was perpetuated on May 19, 2022.

Witness: Kyle A. Tucker



I used a steel tape and magnetic compass in the establishment of the new accessories. I used 14° East declination, the distances are to a 60d spike $\,$ driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.

UNION COUNTY SURVEYOR File Number 012-2022R

> **PROFESSIONAL** LAND SURVEYOR OREGON

REGISTERED

June 2, 2010 JEFFREY'S. HSU 83571

Renewal Date: June 30, 2023