UNION COUNTY SURVEYOR

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner not previously established

DESCRIPTION OF CORNER EVIDENCE FOUND:

No record of subsequent monumentation found in Union County survey records.

See Union County Survey 045-1998

T 1 S R 40 E K - 07

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At position determined by survey, I set a 2½" x 30" aluminum pipe with aluminum cap marked as shown below, 30" in the ground from which:

A 9 inch Tamarack bears $N38^{\circ}E$, a distance of 35.30 feet, marked CN 1/16 S17 BT.

An 11 inch Douglas Fir bears $$32^{\circ}E$, a distance of 41.06 feet, marked CN 1/16 \$17 BT.

I hereby certify that the corner was monumented on October 21, 1998. Witness: Norbert Volny

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
July 17, 1988
RICK G. ROBINSON
2219

Renewal Date December 31, 1998


UNION COUNTY
SURVEYOR

Date Received 10/23/98

Date Filed 16/24/98

Filed By Lynn 7.64.—

Filed By Lynn 7.64.—



I used a steel tape and magnetic compass in the establishment of the new accessories. I used 18° East declination, the distances are to a 60d spike driven into the root crown of the bearing tree. A brass washer marked OPLS 2219 is attached to the BT blaze: