
History of original corner establishment:

None.



Description of corner evidence found:

REGISTERED

PROFESSIONAL LAND SURVEYOR

Jar

OREGON OCT. 17, 1975 BARRY B. BARBOUR 1 0 \$ 1


70

Barry

None.

Description of monument and accessories I established to perpetuate the original location of this corner:

At surveyed point set 1 1/4" x 30" galvanized pipe and brass cap marked: Set pipe 25" in the ground. From which by magnetic declination of N20°E: A 11" Fir bears N61°E., 41.1 ft. scribed CN1/16S26 BT. A 12" Fir bears N52°W., 36.7 ft. scribed CN1/16S26 BT. Painted blazes red and 6" red band around. Placed 54-3s and brass washers stamped PLS 1051 on BTs. Placed 54-4 on a steel fence post 5' south of the corner.



I hereby certify that the above corner monument was established as herein described.

Witnesses: Daniel Rowland Troy Phillips

July 29, 1981

Office ofCounty Surveyor	UNION COUNTY SURVIYOR
Form R6-7100-57 (9/71)	Date Received A OPO-798-276 Date Filed
	By
	File No. 177-84 R