


UNION COUNTY
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner was never set.



No record of subsequent monumentation found in Union County survey records.

Description of corner evidence found:

See Map of Survey Number 015-1992.

Description of monument and accessories I established to perpetuate the original location of this corner:

At position determined by survey, I set a 5/8" x 30" rebar with aluminum cap marked as shown, 26 inches in the ground stone, from which:

A 9" Douglas Fir bears S32°E, 13.95 feet, marked X BT


A 12" Douglas Fir bears N 5°E, 9.48 feet, marked NE 1/16 S 10 BT

Set steel fence post 1 foot south.

There is an E-W fence line 28 feet south.

I hereby certify that the above corner point was perpetuated as hereon described on May 15, 1992.

Whitness;
Pete Crabtree



**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

Duane I. Griffith

OREGON
JULY 10, 1964
DUANE I. GRIFFITH
644

I used a steel tape and magnetic compass in the establishment of new accessories. I used 20° East magnetic declination. The distances are to a 50d spike driven in the right side of the root crown. I attached a brass washer marked OPLS 644 to the BT blaze.

**UNION COUNTY
SURVEYOR**

Date Received 6/16/92

Date Filed 6/20/92

By *Greg Black*

File No. 031-1992R