# CERTIFIED RECORD OF LAND CORNER MONUMENTATION


# HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner originally established by Rufus S. Moore under GLO contract 451, dated June 12, 1882. Surveyor General field notes state:

Set a post 3 ft. long, 3 ins. sq. 24 ins. in the ground for 1/4 sec. cor. marked 1/4 S on W face, from which:

A Pine 10 ins. in dia. bears N53°W, 12 lks. dist. marked 1/4 S BT.

A Pine 9 ins. in dia. bears S62°E 14 lks. dist. marked 1/4 S BT.



## DESCRIPTION OF CORNER EVIDENCE FOUND:

None.

#### SEE SURVEY NUMBER 015-2016

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

#### TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At proportionate position, I set a 2  $\frac{1}{2}$ " x 30" aluminum pipe monument, with 2  $\frac{1}{2}$ " aluminum cap attached, marked as shown below, 26" in the ground, in a collar of stone 1 ft. diam., from which:

## NEW BEARING OBJECTS:

A 9 inch Lodgepole Pine bears North 20° East, a distance of 23.75 feet, marked 1/4 S10 BT. A 10 inch Lodgepole Pine bears South 85° East, a distance of 12.05 feet, marked 1/4 S15 BT. A 9 inch Douglas Fir bears South 12° West, a distance of 12.75 feet, marked 1/4 S15 BT. A 5 inch Douglas Fir bears North 45° West, a distance of 5.00 feet, marked 1/4 S10 BT.


Set a steel fencepost approx. 1 ft. North of corner monument. I hereby certify that this monument was set May 13, 2016.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
June 2, 2010

JEFFREY S. HSU
83571

Renewal Date: June 30, 2017



I use a steel tape and magnetic compass in the establishment of the accessories.

Magnetic declination used was 15° East.

Distances are to a 60d spike in the right hand side of the root crown of the bearing trees.