


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

C-7

History of original corner establishment:

NONE: Corner established this survey.



Description of corner evidence found:

NONE: Corner established this survey.

Description of monument and accessories established to perpetuate the original location of this corner:

Set a 2½ inch aluminum cap on a 2 inch aluminum pipe 30 inches long and projecting 4 inches out of the ground with a surrounding rock mound and a 6 foot steel fence post alongside with a sign 54-9 attached.

Aluminum cap marked thus:

T 2 S R 38 E

C  $\frac{1}{4}$  S 5

1983

ORLS 1639

New bearing trees established:

A fir 9 ins diam bears N 17° W, 40.4 ft dist marked C 1/4 S 5 BT

A fir 10 ins diam bears S 43° E, 24.3 ft dist marked C 1/4 S 5 BT

Each new bearing tree has a sign 54-3 attached below a 6 inch band of red paint and has a brass washer marked PLS 1639 nailed flush with BT blaze. A sign 54-4 is attached on the opposite side of tree from BT blaze.

I hereby certify that the above described corner monument was properly established by me on Nov. 1, 1983, and witnessed by Jim DeMastus.

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*William L. Hanley*

OREGON  
JULY 14, 1978  
WILLIAM L. HANLEY  
1639

Office of County Surveyor ..... County of Union  
State of Oregon ..... I hereby certify that the within instrument was filed in this office  
for record on the ..... day of ..... , 19.....

(COUNTY OFFICIAL)

(DEPUTY)

Form R6-7100-57 (9/71)

<b>UNION COUNTY SURVEYOR</b>
Date Received <u>11-10-83</u>
Date Filed <u>11-14-83</u>
By <u>G. LANGLITZ, DEPUTY</u>
File No. <u>397-83 R</u>