

UNION COUNTY SURVEYOR

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner not originally established by GLO Contract.

No record of subsequent monumentation found in the Union County monumentation records

DESCRIPTION OF CORNER EVIDENCE FOUND:

No evidence of any corner monument

See Survey Number 042-2001

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position determined by survey, I set a 2 1/2" x 30" aluminum pipe with aluminum cap marked as shown below, 26" in the ground, from which;

NEW BEARING TREES:



A 19" diameter Douglas Fir bears North 36° East, a distance of 41.50 feet marked S1/16 S16 BT.

A 17" diameter Ponderosa Pine bears South 51° East, a distance of 7.75 feet, marked S1/16 S16 BT.

(No tree available in Section 17)

Set steel fence post approximately 1 ft. west of corner monument.

I hereby certify that the corner was monumented on November 14, 2001.
Witness: Norbert W. Volny and Gregory T. Blackman Jr.



I used a steel tape and magnetic compass in the establishment of the new accessories. I used 18° East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing tree. I attached a brass washer marked OPLS 2219 to the BT blaze.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Rick G. Robinson

OREGON
July 17, 1988
RICK G. ROBINSON
2219

Renewal Date December 31, 2002

**UNION COUNTY
SURVEYOR**

Date Received 11/29/01

Date Filed 12/05/01

Filed By *Greg T. Black*

File Number 048-2001 R