


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

CORNER NOT SET IN ORIGINAL SURVEY by Rufus S. Moore in 1882.



No record of monumentation found in the County Record.

Description of corner evidence found:

Description of monument and accessories I established to perpetuate the

original location of this corner I set a 2 1/2" x 30" galvanized iron pipe with brass cap 15 inches in the ground and raised a mound of stone at the corner position, from which BTs.


A pine 11" in diameter bears N 80-E a distance of 20.2 feet
Marked C $\frac{1}{4}$ S 16 BT.

A pine 10" in diameter bears N 85 W a distance of 84.0 feet, marked C $\frac{1}{4}$ S 16 BT.

I placed a nail and a brass washer marked O.P.L.S. 991 at the BT. blaze.

I used a steel tape and a magnetic compass with 20 degrees declination East set into the compass.

I set a steel fence post with a sign 5.0 feet East of the corner.



REGISTERED PROFESSIONAL LAND SURVEYOR

Gregory T. Blackman
OREGON
JUL 3, 1979
GREGORY T. BLACKMAN
991

Office of Union County of Union
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 18 day of Sept, 1978
J. V. [Signature] by [Signature]
(COUNTY OFFICIAL) (DEPUTY)

UNION COUNTY SURVEYOR

Date Received _____

Date Filed _____

By _____

File No. 414-84 R
GBO 796 333