


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

CORNER NOT SET IN ORIGINAL SURVEY by Rufus S. Moore in 1882.
No record of monumentation was found in the County records.



Description of corner evidence found:

None

Description of monument and accessories established to perpetuate the original location of this corner: At corner position I set a 2 1/2"x30" galvanized iron pipe 20" in the ground and built a mound of stone, from which New BTs.


A pine 12" in diameter bears N 2 W a distance of 55.5 feet marked SE 1/16 BT.

A pine 12" in diameter bears N 76 E a distance of 32.3 feet, marked SE 1/16 BT.

I placed a nail and a brass washer marked O.P.L.S. 991 at the BT. blaze.

I used a steel tape and a magnetic compass with 20 degrees East declination set into the compass.

I set a steel post with a sign 5.0 feet North of the corner.



REGISTERED PROFESSIONAL LAND SURVEYOR

Gregory T. Blackman

OREGON
JUL 3 1978
GREGORY T. BLACKMAN
991

Office of Surveyor County of Union
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 14 day of Sept 1978
J. Voelz by G. T. Blackman
(COUNTY OFFICIAL) (DEPUTY)

UNION COUNTY SURVEYOR
Date Received _____
☆ GPO 799-509
Date Filed _____
By _____
File No. <u>418-84R</u>