


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:
Corner not previously established.



DESCRIPTION OF CORNER EVIDENCE FOUND:
None.

SEE SURVEY NUMBER 003-2015

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At position determined by survey, I set a 5/8" x 30" iron pin, 30" in the ground, with a 2 1/2" aluminum cap, marked as shown below, from which:


A 5/8" x 15" iron pin bears South 1°00' West, a distance of 20.00 feet, with 1 1/2" aluminum cap marked BGB SURVEY MARKER S RP.

A 5/8" x 30" iron pin bears West, a distance of 20.00 feet, with 1 1/2" aluminum cap marked BGB SURVEY MARKER W RP.

Set a steel fence post approximately 0.5 feet North of corner monument. Monument falls approximately 15 feet West of a fence corner.

I hereby certify that the corner was monumented on January 26, 2015

REGISTERED
PROFESSIONAL
LAND SURVEYOR



OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2015

BAGETT - GRIFFITH & BLACKMAN

T3S R40E
E 1/16
C ————— C
S 31
2015
OPLS 83571

**UNION COUNTY
SURVEYOR**

Date Received 1/29/15
Date Filed 1/29/15
Filed By [Signature]
File Number 006-2015R

I used a Leica GS-15 RTK GPS in the establishment of the accessories. Bearings and distances are to the center of the aluminum caps. Basis of bearings is as per Survey Number 003-2015.